

## Menu

HISTORY FILE MAP for year 2003

REALTIME


PLAYBACK

RECALLED REALTIME

RECALLED PLAYBACK

273.08:16-08:25 9m real-time 1024bps data loss and 7m (273.03:05-03:12) 512bps data lost due to downlink control channel problems during 2k playback. DR M101924 refers.

273.15:58-16:05 7m realtime 1024bps data lost due to long bit rate change from 2048bps at DSS25. No DR was raised.



278.16:21-16:35 14m 1024bps realtime data and 31m (278.11:03-11:33) 512bps playback data lost due to cable wrap position switch failure at DSS25. DR G103445 refers.

278.17:55-18:28 33m 1024bps realtime data and 1h 9m (278.07:17-08:26) 512bps playback data lost due to cable wrap position switch failure at DSS25. DR G103445 refers.